

**To:** rlaw@demaximis.com[rlaw@demaximis.com]  
**From:** Vaughn, Stephanie  
**Sent:** Wed 2/6/2013 2:01:23 PM  
**Subject:** Fw: Rm 10.9 oversight February 5, 2013

Rob -- Please give me a call when you can. I think it was pretty clear that they weren't supposed to start work until Tuesday.

Thanks

----- Forwarded by Stephanie Vaughn/R2/USEPA/US on 02/06/2013 08:42 AM -----

**From:** "Kirchner, Scott" <KirchnerSF@cdmsmith.com>  
**To:** Stephanie Vaughn/R2/USEPA/US@EPA  
**Cc:** "Buckrucker, Elizabeth A NWK" <Elizabeth.A.Buckrucker@usace.army.mil>, "Budney, Sharon" <BudneySL@cdmsmith.com>, "Tsang, Frank" <TsangC@cdmsmith.com>, "Rakowski, Jeffrey" <RakowskiJJ@cdmsmith.com>, "Molnar, George" <MolnarGC@cdmsmith.com>  
**Date:** 02/06/2013 07:42 AM  
**Subject:** FW: Rm 10.9 oversight February 5, 2013

Stephanie,

On Tuesday February 5, 2013, CDM Smith oversight staff observed sediment coring in support of the RM 10.9 removal action program. Two locations, RM10.9D-0338 and -0351, were sampled; however, crews were unable to collect all the needed cores at -0351, and plan to return and complete on Wednesday the 6<sup>th</sup>.

During sampling activities, an outfall behind Lyndhurst Pumpstation 4 opened up and discharged during sampling at location RM10.9D-0351 which was located approximately 100' southwest.

Field crews informed oversight staff that location RM10.9D-0350 was sampled sometime on Monday the 4<sup>th</sup> after mobilization. Oversight staff were unaware of CPG's plans to conduct any sampling on Monday so no oversight was performed at that location.

Sincerely

**Scott F Kirchner**, CHMM | Project Manager | CDM Smith  
110 Fieldcrest Avenue, #8, 6th Floor | Edison, NJ 08837 | phone/fax (732) 590-4677 | cell (732) 713-6824